

Trent Valley Kart Club

FIRE EXTINGUISHER VISIT REPORT



Please Note: Only the Fireguard Limited company has the BAFE certification. If you are not under the Fireguard Company and require the BAFE certification, please advise us and we will swap the company that handles your account. This will not occur any additional fees.

British Standards recommends the Fire Extinguishers are Services on an Annual Basis

FireGuar South Anston F West Yorkshire	584023		Fireguard S.A.F.E. W.Y.F.S.		The Fire Ho Heritage Heritag Hemin Barn S73	e House e Court gfield sley	FIRE EXT	TINGUISHEF Report P.	R VISIT AGE 1 OF 4
COMPANY NAM	E	Trent Valley Kar	t Club			TECHNICIAN		Dean Watson)
SITE ADDRESS		P.F International H Brandon	Cart Circuit			DATE		5/5/2023 11:3	
		Grantham				QUOTED WORK (R	FF)	0/0/2020 11.0	
Contact Name &	Number	NG32 2AY Danielle/ Nigel/Cla 01632 626424 (ja	are mes -site contact 0	7919367091)	PO NUMBER			1	
				1	WORK CARRIED OL	JT		-	
Equipment	Size	Extinguishers Serviced	Passed	Failed	Extinguishers Installed	Price of Extinguisher	Total cost of new Extinguishers	ID signs installed	Disposal
WATER	3LTR								
	6LTR 9LTR		╂────╂						
WATER WITH	3LTR								
ADDITIVE	6LTR		\square						
CO2	9LR 2KG		++			E Image: Constraint of the second s		_	
	5KG								
FOAM	1LTR		\square						
	2LTR 3LTR		╂────╂			<u></u>			
	6LTR								
	9LTR								
WET CHEMICAL	2LTR 3LTR		┼───┼					+	+
	6LTR								
POWDER	1KG								
	2KG 4KG		┼───┼			<u> </u>			
	4KG 6KG	2	0	2	2	£62.50	£125.00		2
	9KG								
MULTI CHEM	2LTR 3LTR		┼───┼						
	4LTR								
	6LTR								
F. BLANKET			┼───┼			<u> </u>			
			 			<u> </u>		+	
TOTALS		2	0	2	2		£125.00	0	2
071	1			EXT	TRA ITEMS PURCHA	SED			Total
QTY 1	Fuel Surd	charge			ITEM			PPU £2.50	TOTAL £2.50
		5							
TOTAL COST									£2.50
					COSTINGS				-
SERVICING COST FIXED SERVICING		•			TOTAL COST				£0.00
NEW FIRE EXTIN		1			TOTAL COST TOTAL COST				£125.00
ATTENDANCE FE	E / FUEL S				TOTAL COST				
SIGNS COST PER					TOTAL COST				£0.00 £0.00
DISPOSAL COST					TOTAL COST TOTAL COST				£0.00 £2.50
					TAL AMOUNT PAY	ABLE			
TOTAL COST (EX	CL. VAT)							£127.50	
TOTAL COST (IN	C. VAT)							£153.00	
PAYMENT METHOD									
Cash		1	(Cheque		<u> </u>		Account	
				EI	NGINEER COMMEN	115			

Image: Control of the second secon	Herita F.E. Herita Hem F.S. Ba S7	House Group ge House age Court ingfield rnsley 3 OHZ Is appropriate signage fitted? Yes No N/A Comments:	FIRE EXTINGUISHER VISIT REPORT PAGE 2 OF 4					
Image:		Image:						
Is there a log book on site?								
Yes								
No								
N/A								
Has the log book been completed?								
Yes								
No								
N/A								
Comments:								
The Singhama Casure have earlied the first outleastick	SERVICING ST		e in accordance with the requirements and frequencies					
indica According to BS5306 part	ted by BS5306 part 3 and refilled when re 3, it is the duty of the responsible person re extinguishers are inspected in accordar	quired in accordance with BS5306 in the premises to inspect extingui	part 9. shers at monthly intervals.					
	WASTE TRANSFER							
If any fire extinguishers are taken away from your site (identified in the disposal section), please see below the waste transfer and registration information. Waste Transfer Registration Number: CBDL285178. EWC Code: 16.05.05 Some Fire Extinguishers are used for training and the remainder are broken down (the aluminium, plastic, steel & contents are all separated). Each component is collected by a 3rd party for recycling (powder is used for fertilizer). Copies of the 3rd parties waste transfer information is available upon request.								
	COMPLE	ΓΙΟΝ						
CUSTOMER NAME CUSTOMER EMAIL ADDRESS	Danielle clare@tvkc.co.uk							
ACCOUNT DEPARTMENT EMAIL ADDRESS	Gai 5 10 10 10 10 10 10 10 10 10 10 10 10 10							
DATE	5/5/2023 12:58 pm							
SIGNATURE	A		\supset					
CUSTOMER COMMENTS/FEEDBACK								

FIRE	Fireguard	The Fire House Group Heritage House	Fire Extinguisher Visit
FireGuard Limited 11399 579991 South Anston Fire Extinguishers 11399 586923	S.A.F.E.	Heritage Court Hemingfield	REPORT
West Yorkshire Fire & Security 1111 Viz Zhadarin www.thdfichensegroup.co.uk abara@bafietensegroup.co.uk	W.Y.F.S.	Barnsley S73 0HZ	PAGE 3 OF 4

	Recommendations/Replacements - If not completed on the 1st visit									
	LOCATION/DESCRIPTION	ITEM	PPU	TOTAL						
				-						
┝──										
<u> </u>										

TOTAL COST OF RECOMMENDATIONS/REPLACEMENTS							
TOTAL COST (EXCL. VAT)	£0.00						
TOTAL COST (INC. VAT)	£0.00						

Have the replacements been discussed with the customer?	Yes	No
Comments:		

П

OTHER SERVICES AVAILABLE						
ITEM	TICK					
Fire Risk Assessments						
Fire Alarm Installation / Service						
Emergency Light Installation / Service						
Fire Marshal Training						
Live Extinguisher Training						
Fire Suppression Installation / Service						
Fire Sprinkler Installation / Service						
Gas Systems Installation / Service						
Pat Testing						
Periodic Fixed Wire Testing						
CCTV Installation / Service						
Door Access Installation / Service						
Nurse Call Systems						

FIRE HOUSE Group
FireGuard Limited 01700 570001 South Anston Fire Extinguishers 01700 584023
West Yorkshire Fire & Security 01134 200000 www.thefndewagroup.co.dx

Fireguard

S.A.F.E.

The Fire House Group Heritage House Heritage Court Hemingfield Barnsley S73 0HZ

FIRE EXTINGUISHER VISIT REPORT

PAGE 4 OF 4

DATE: ^{5/5/2023 11:37 am} TECHNICIAN: Dean Watson ASSET LIST:													
	FIRE EXTINGUISHER DTR DATES FIRE EXTINGUISHER TOTAL 2021 2023 2024 2026 2027 2028 2030 2031 2032										2022		
FIRE EXTINGUISHER	TOTAL	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
1KG POWDER	_												
2KG POWDER													
3KG POWDER													
4KG POWDER													
6KG POWDER	2								2				
9KG POWDER													
1LTR FOAM													
2LTR FOAM													
3LTR FOAM													
6LTR FOAM													
9LTR FOAM													
3LTR WATER													
6LTR WATER													
9LTR WATER													
2LTR WET CHEMICAL													
3LTR WET CHEMICAL													
6LTR WET CHEMICAL													
2KG CO2													
5KG CO2													
FIRE BLANKET													
TOTAL NUMBER OF EXTINGUISHERS AND FIRE BLANKETS ON SITE: ²													
				FOF	R ENGINEE	RS USE ON	ILY						
SITE ADDRESS & LOCATION NO Trent Valley Kart Club P.F International Kart Circuit Brandon Grantham NG32 2AY	P.F International Kart Circuit Brandon Grantham												



Certificate of Inspection Fire Extinguishers

Date: 5/5/2023

Inspection carried out at: Trent Valley Kart Club P.F International Kart Circuit Brandon Grantham NG32 2AY

Technicians Name: Dean Watson

We hereby certify all the Fire Extinguishers at the above premises was inspected on the above date in accordance with BS5306/European Directives.

Routine Inspection by user:- BS5306-3:2017 Part 3 section (6) Recommends the user to regularly inspects all extinguishers, replacement charges etc. to make sure that they are in the proper position and are in working order.

The inspections should be carried out annually and you are advised to retain this certificate as proof of an inspection.



The Fire House Group Heritage House, Heritage Court Hemingfield, Barnsley S73 0HZ

Extinguisher Type	On Site	Passed	Failed
Dry Powder	2	2	0
Water	0	0	0
Co2	0	0	0
Foam	0	0	0
Wet Chemical	0	0	0
Fire Blanket	0	0	0
Hose Reel	0	0	0
Multi Chem	0	0	0
D Class	0	0	0

Phone: 0844 693 1150



Email:

admin@thefirehousegroup.co.uk



DID YOU KNOW...

- Fire Alarm Systems should be serviced on a 6 monthly basis?
- Emergency Lighting should be serviced on an annual basis?
- Fire Risk Assessments should be conducted then reviewed on an annual basis?
- Periodic Inspections should be conducted on a 5 yearly basis?
- You should have employees that are trained fire marshals?
- Fire Extinguishers should be serviced on an annual basis?

DID YOU ALSO KNOW...

We can also offer the below:

- Fire Extinguisher Sales/Service
- Fire Alarm Installation/Service
- Emergency Lighting Installation/Service
- Fire Risk Assessments
- PAT Testing

- CCTV Installation/Maintenance
- Door Access Installation/Maintenance
- Gas Inspection Certificates
- Intruder Alarm Installation/Maintenance
- Fire Training

NEW SERVICES...

- Electrical Installations
- New Sockets
- New Lighting Installations

- Electrical Testing
- Fuse Board Upgrades/Changes
- Periodic Inspection

If you need assistance with any of these services please give us a call for a Free No Obligation Quotation on:

0844 693 1150

OR

Visit our website:

www.thefirehousegroup.co.uk